Page 2

Application/Control Number: 10/791,380

Art Unit: 3751

An examiner's amendment to the record appears below. Should the changes and/or additions be unacceptable to applicant, an amendment may be filed as provided by 37 CFR 1.312. To ensure consideration of such an amendment, it MUST be submitted no later than the payment of the issue fee.

In the specification: page 3, paragraph 14; line 1, "as" has been changed to –providing a surface at-, line 2, -extending- has been inserted between "13" and "to", line 4, "prettification" has been changed to –esthetics-; in paragraph 15, line 1, "installed" has been changed to –formed- and line 16, 'holes" has been changed to –hole-; and paragraph 19 has been rewritten as follows: -The fillisters 14, formed on wall mount 10, comprise a sidling taper or side walls that taper away from the surface 11, as best viewed in Fig. 4.-. These changes have made in order to provide for proper grammar.

Any inquiry concerning this communication or earlier communications from the examiner should be directed to Charles E. Phillips whose telephone number is 571-272-4893. If attempts to reach the examiner by telephone are unsuccessful, the examiner's supervisor, Justine Yu, can be reached on 571-272-4835. The fax phone number for the organization where this application or proceeding is assigned is 571-273-8300.

Information regarding the status of an application may be obtained from the Patent Application Information Retrieval (PAIR) system. Status information for published applications may be obtained from either Private PAIR or Public PAIR. Status information for unpublished applications is available through Private PAIR only. For more information about the PAIR system, see http://pair-direct.uspto.gov. Should